

! " #

! (Nb 0!)	" 99.5%	99.5%
# (Ti)	\$ 0.002%	%0.002%
& (Cu)	\$ 0.002%	%0.002%
' (Si)	\$ 0.005%	%0.005%
((As)	\$ 0.003%	%0.003%
) (Cr)	\$ 0.002%	%0.002%
* (Al)	\$ 0.003%	%0.003%
+ (Sn)	\$ 0.002%	%0.002%
, (Bi)	\$ 0.002%	%0.002%
- (Mo)	\$ 0.003%	%0.003%
. (W)	\$ 0.003%	%0.003%
/ (Mn)	\$ 0.002%	%0.002%
O (Ta)	\$ 0.1%	%0.1%
1 (Fe)	\$ 0.005%	%0.005%
2 (Pb)	\$ 0.002%	%0.002%
3 (Ni)	\$ 0.002%	%0.002%
4 (Sb)	\$ 0.002%	%0.002%
5 (Mg)	\$ 0.002%	%0.002%
6 (F)	\$ 0.08%	%0.08%

\$ 8.1%